

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

407  
SW  
1/2-1  
0.647 mi.  
3418 ft.

VAULT VS6102  
WEST 22ND ST  
BROOKLYN, NY

NY Spills S103936550  
N/A

Relative:  
Higher

Actual:  
2 ft.

SPILLS:

Name: VAULT VS6102  
Address: WEST 22ND ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9900892 / 2002-06-13  
Facility ID: 9900892  
Facility Type: ER  
DER Facility ID: 185394  
Site ID: 224311  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1999-04-23  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 1999-04-23  
CID: 205  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-04-23  
Spill Record Last Update: 2002-06-13  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: CALLER  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL CON ED E2MIS NOTES 5-04-99 Aprrox. 1pt of an unknown oil on 400 gals. of water. Contained to structure, no sewer or waterway affected. Unit pressure tested, good. Records dated 3/97 show PCb to be 8ppm. Lab Seq#00-04178 <1ppm UPDATE: 4/27/99 STRUCTURE MAKES A TREMENDOUS AMOUNT OF WATER. WILL HAVE TO MAKE ARRANGEMENTS FOR TWO LARGE TANKERS AND AN EQUIP. GP. MEET. UPDATE: 11-JAN-2000 ; 1700HRS O/S CAMPANILE REPORTS WHILE FLUSH DEPT WAS CLEANING STRUCTURE THEY SUSPECTED THAT A LARGER AMOUNT OF OIL WAS IN STRUCTURE THAN ORIGINALLY STATED. CALLED NETWORK EQUIPMENT DEPT TO LOCATION TO INSPECT UNIT. EQUIP GROUP FOUND UNIT BELOW MIN AND REQUESTED OFF ON A PRIROITY ONE. PRESSURE TESTED UNIT WHEN UNIT WAS OUT. IT DID NOT HOLD PRESSURE LOST 35 GALLONS OF OIL FROM TRANSFORMER. 3.5 INCHES BELOW MIN. AT THIS TIME 5 GALLONS OF OIL ON TOP OF 100GALLONS OF WATER. MR CAMPANILE IS ESTIMATING 30 GALLONS OF OIL WAS REMOVED BY TANKER DURING THE DAY. UPDATE: 11-JAN-2000 1713 I REQUESTED MR CAMPANILE TO CALL ERT FOR FURTHER ASSISTANCE ON THIS MATTER. UPDATE: 11-JAN-2000 1715HRS MR CAMPANILE REPORTS SPOKE TO B WALLACE OF ERT AND SAID TO UPDATE INFO. NO FURTHER ACTION REQUIRED. CLEAN UP WILL CONTINUE WHEN TRANSFORMER IS REMOVED IN THE AM. 1/12/00--1700hrs---j.lopori flush

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

reports cleanup completed tag# 06800 removed NOTE: TRANSFORMER WAS DRAINED OF 215 GALS. OF OIL AND REMOVED. STRUCTURE WAS DOUBLE WASHED WITH SLIX. ALL LIQUID WASTE WAS REMOVED BY TANKER. IT WAS IMPOSSIBLE TO CEMENT THE SUMP DUE TO THE AMOUNT OF WATER COMING UP THROUGH IT. THIS, OF COURSE, WOULD ALSO INDICATE THAT IT WAS IMPOSSIBLE FOR ANY OIL TO GO INTO THE SUMP. INCIDENT IS CLOSED. UPDATE: 4/9/02 @ 1255 HRS. TRANSFORMER WAS REPLACED ON JAN. 12 2000."  
"1 PT ON 400 GALLONS WATER. CON ED # 124401."

Remarks:

All Materials:

Site ID: 224311  
Operable Unit ID: 1079664  
Operable Unit: 01  
Material ID: 308009  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported